

# **AB803**

JUNE 2013 JUIN 2013 JUNIO 2013













The Ideal Choice for Outstanding Braking Performance.

Modern CV air brake systems generate enormous frictional forces and stresses during operation — far in excess of those present in hydraulic systems. That's why you need a CV brake pad specifically formulated for air brake applications.

Abex air brake pads have patented cast iron backplates and an integrally molded V-grove design which greatly improves heat dispersal and eliminates excessive material stress. When you need a brake that stops faster with enhanced durability for long lasting performance — Abex is the ideal choice for all of your commercial vehicle braking needs.

**OE** Material(s)

**Thermal Underlayer** 

Green Coating for Rapid Bedding-In

**V-Groove Design** 


**Cast Iron Back Plate** 

- Global leader in OE applications
- Friction materials engineered for specific applications
- Compatible with ABS/ESP systems
- Safe and reliable
- High performance under most temperatures and conditions
- Reduces downtime
- Extended life and reduced rotor wear
- Includes complete hardware kit
- Meets R90 European Standards

New patented cast iron backplate technology for safer and more efficient braking performance

- Utilizes the latest advances in proprietary back plate cast iron technology
- Lighter than standard backplates
- Secure bond between pad material and backplate with less risk of corrosion

The Future of CV Brake Technology.







# CV Trouble Shooter Brake Pads and Rotors

Periodic inspection of the braking system is essential. It is recommended that when it is necessary to replace brake rotors it is safe practice to also replace brake pads. Both should always be replaced across the axle.




APPEARANCE	Rotor featuring scored surface.
CAUSE	Pads fitted with friction material too harsh for the rotor or new pads assembled on excessively worn out rotors.
EFFECT	Reduction in braking performance and possible imbalance on the affected axle during braking.
REMEDY	<ul><li>Replace the pads.</li><li>Check rotor condition and minimum thickness.</li></ul>

If necessary, replace the rotor. · Check for the quality of the spare parts used.



APPEARANCE	Contaminated pad friction material.
CAUSE	Contamination by an oily substance or solvent.
EFFECT	Reduction in braking performance and possible imbalance during braking.
REMEDY	Replace the pads.

• Check the rotors on the axle.




APPEARANCE	Uneven brake pad wear.
CAUSE	One of the calipers has become stuck or does not return correctly to the rest position.
EFFECT	Reduction in braking performance and possible imbalance on the involved axle, during braking.
REMEDY	<ul><li>Replace the pads.</li><li>Brake calipers should be checked.</li></ul>



100000	AND A STATE OF THE PARTY OF THE
APPEARANCE	Excessively worn out rotors and pads.
CAUSE	Possible contamination of the friction material by sand, mud or earth or incomplete return of the caliper gear.
EFFECT	Excessive wear of one or more brake pads, resulting in damage where the pad has not been fitted with a wear indicator.
REMEDY	<ul> <li>Replace the pads.</li> <li>Check rotor condition and minimum thickness.</li> <li>If necessary, replace both rotors on the axle.</li> </ul>



APPEARANCE	Friction includes metal pick-up.
CAUSE	High temperature generated between brake pad and rotor in wet conditions.
EFFECT	Wear of the affected brake rotor with typical metal rubbing noise during braking.
REMEDY	Replace the pads. Check rotor condition and minimum thickness. If necessary, replace both rotors on the axle.




APPEARANCE	Glazed pad friction material.
CAUSE	Very low duty applied on the brakes, i.e. brake applications with low speed and low pressure.
EFFECT	Reduction in braking performance and typical noise (squeal) while braking.
REMEDY	<ul> <li>If glazing is not too heavy can try to recondition the surface by some mileage of medium/hard brake duty, otherwise replace the pads.</li> <li>Check the rotor condition and minimum thickness.</li> </ul>




# CV Trouble Shooter Brake Pads and Rotors

Periodic inspection of the braking system is essential. It is recommended that when it is necessary to replace brake rotors it is safe practice to also replace brake pads. Both should always be replaced across the axle.



APPEARANCE	Rotor surface features 1st and 2nd degree crack.
CAUSE	Too intensive use of brakes due to the track features or to the carried load.
EFFECT	Possible unexpected rotor mechanical collapse, particularly with 2nd degree crack.
REMEDY	<ul> <li>Immediate replacement of brake rotors and pads, particularly with 2nd degree crack, when one of the cracks is travelling from OD to ID.</li> <li>Brake calipers should be checked.</li> </ul>



	and the second s
APPEARANCE	Damaged edges to the friction material (edge-crumbling).
CAUSE	Brake pad has become stuck in the caliper. The parts used do not comply with the correct sizes and specifications.
EFFECT	Early pad deterioration and uneven rotor wear.
REMEDY	<ul> <li>Replace the pads.</li> <li>Check for correct caliper operation.</li> <li>Check rotor condition and minimum thickness.</li> </ul>

• If necessary, replace both rotors on the axle.




APPEARANCE	Pads on the same axle featuring uneven wear.
CAUSE	Incorrect return of one caliper on the same axle.
EFFECT	If the axle involved is the directional one, this fault may result in vehicle instability during brake release.
REMEDY	<ul> <li>Replace the pads.</li> <li>Check for the proper caliper operation.</li> <li>Check rotor condition and minimum thickness.</li> </ul>

• If necessary, replace both rotors on the axle.



APPEARANCE	Pad with surface cracks.
CAUSE	Excessive load or high friction material temperature.
EFFECT	Possible detachment of friction material resulting in a reduction in braking performance.
REMEDY	<ul> <li>Replace the pads.</li> <li>Check for correct caliper operation.</li> <li>Check rotor condition and minimum thickness.</li> <li>If necessary, replace both rotors on the axle.</li> </ul>



APPEARANCE	Detached friction material.
CAUSE	Possible excessive load or heavy braking, along with the choice of unsuitable parts.
EFFECT	Reduction in braking performance and typical noise (squeal) while braking.
REMEDY	<ul> <li>Replace the pads.</li> <li>Check the rotor condition and minimum thickness.</li> <li>Despite having a wear indicator, it is pecassary to che</li> </ul>

every six months.

the pad condition during normal brake inspection and/or




E-127-7-120-7-140-7-1-1-1-1	
APPEARANCE	Blue stripes on the rotor indicating a physical change due to overheating.
CAUSE	Intensive use of brakes for prolonged braking or improper downhill braking.
EFFECT	Brake rotor overheating which may result in contact surface distortion and cracks.
REMEDY	<ul> <li>Immediate replacement of brake rotors and pads.</li> <li>During the first 150 miles after replacement, sharp braking should be avoided in order to allow for the correct bedding-in of the newly fitted components.</li> </ul>





Brake Pad:	ADB1203FE
Туре:	Knorr SB/SN7
Applications:	City Bus
X-ref:	5013257
FMSI:	8323-D1203
WVA:	29179
Material:	4567
Comments:	Includes OE style Hardware Kit










Brake Pad:	ADB1203AFE
Туре:	Knorr SB/SN7
Applications:	Over-the-Road Coach
X-ref:	5013257 1138162F
FMSI:	8323-D1203
WVA:	29179
Material:	4550
Comments:	Includes OE style Hardware Kit











Brake Pad:	ADB1310FE
Туре:	Meritor D-Elsa 2
Applications:	City Bus
X-ref:	MDP5097 N508206052
FMSI:	8425-D1310
WVA:	29156
Material:	4567
Comments:	Includes OE style Hardware Kit













Brake Pad:	ADB1310AFE
Туре:	Meritor D-Elsa 2
Applications:	Over-the-Road Coach
X-ref:	MDP5060 N508206051
FMSI:	8425-D1310
WVA:	29156
Material:	4568
Comments:	Includes OE style Hardware Kit















Brake Pad:	ADB1311
Туре:	Meritor EX225H2
Applications:	Bus and Coach
X-ref:	Meritor KIT2252H2CD MCI #04-01-1113
FMSI:	8426-D1311
WVA:	29187
Material:	4576
Comments:	Includes OE style Hardware Kit













Brake Pad:	ADB1312
Туре:	Meritor D-Lisa
Applications:	City Bus
X-ref:	68932068NZP
FMSI:	8427-D1312
WVA:	29090
Material:	4567
Comments:	Includes OE style Hardware Kit














Brake Pad:	ADB1369
Туре:	Bendix® ADB22XTM™ Knorr SK7
Applications:	SAF Tractor-Trailer
X-ref:	802078, K070796
FMSI:	8479-D1369
WVA:	29158
Material:	4550
Comments:	Includes OE style Hardware Kit











Brake Pad:	ADB1407FE
Туре:	Meritor D3/D-Elsa1
Applications:	City Bus
X-ref:	MDP5065
FMSI:	8515-D1407
WVA:	29210
Material:	4567
Comments:	Includes OE style Hardware Kit
















Brake Pad:	ADB1407AFE
Туре:	Meritor D3/D-Elsa1
Applications:	Over-the-Road-Coach
X-ref:	MDP5038
FMSI:	8515-D1407
WVA:	29210
Material:	4568
Comments:	Includes OE style Hardware Kit












Brake Pad:	ADB1438
Туре:	Wabco Pan19-1
X-ref:	12999737VT
FMSI:	8556-D1438
WVA:	29159
Material:	4569
Comments:	No Kit.










Brake Pad:	ADB1441
Туре:	Bendix® ESD-225™
X-ref:	976003
FMSI:	8577-D1441
WVA:	29120
Material:	4550
Comments:	Includes OE style Hardware Kit










Brake Pad:	ADB1517
Туре:	Wabco Pan19-2
X-ref:	12999747VT
FMSI:	8726-D1517
WVA:	29141
Material:	4572
Comments	No Kit










Brake Pad:	ADB1518	
Туре:	Wabco Pan17	
X-ref:	12999703VT	
FMSI:	8727-D518	
WVA:	29088	
Material:	4551	
Comments:	No Kit.	












Brake Pad:	ADB1525FE	
Туре:	Meritor DX195	
X-ref:	KIT 195020	
FMSI:	8733-D1525	
WVA:	29155	
Material:	4550	
Comments:	Includes OE style Hardware Kit	










Brake Pad:	ADB1526	
Туре:	Meritor DX225	
X-ref:	KIT225020	
FMSI:	8734-D1526	
WVA:	29150	
Material:	4567	
Comments:	Includes OE style Hardware Kit	











Brake Pad:	ADB1527	
Туре:	Haldex ModulX® DB22	
X-ref:	790-22008	
FMSI:	8735-D1527	
WVA:	29143	
Material:	4550	
Comments:	Includes OE style Hardware Kit	









Competitor	Competitor Part	Abex Part
Prevost	611049	ADB1203AFE
Prevost	611049	ADB1203FE
Bendix	976003	ADB1441
MCI	04-01-1019	ADB1312
MCI	04-01-1113	ADB1311
Meritor - Wabco	12999703VT	ADB1518
Meritor - Wabco	12999737VT	ADB1438
Meritor - Wabco	12999747VT	ADB1517
Textar	292021	ADB1203AFE
Textar	29202-300 1 4 T7400	ADB1203AFE
Bendix	5013257	ADB1203AFE
Bendix	5013257	ADB1203FE
Meritor	68932068NZP	ADB1312
Haldex	790-22008	ADB1527
Bendix	802078	ADB1369
Performance Friction	9175.10	ADB1407AFE
Performance Friction	9175.10	ADB1407FE
Performance Friction	9178.10	ADB1203AFE
Performance Friction	9178.10	ADB1203FE
Performance Friction	9183.10	ADB1312
Performance Friction	9190.10	ADB1310AFE
Performance Friction	9190.10	ADB1310FE
Raybestos	ATD1203HD	ADB1203
Raybestos	ATD1310HD	ADB1310
Raybestos	ATD1310HD	ADB1310AFE
Raybestos	ATD1311HD	ADB1311
Raybestos	ATD1312HD	ADB1312
Raybestos	ATD1369HD	ADB1369
Raybestos	ATD1407HD	ADB1407
Raybestos	ATD1407HD	ADB1407AFE
Bendix	ADB22X	ADB1369
Marathon	CBP-HDXO1	ADB1310AFE
Marathon	CBP-HDXO1	ADB1310FE

Competitor	Competitor Part	Abex Part
Marathon	CBP-MTR225	ADB1311
Marathon	CBP-PRVO1	ADB1203AFE
Marathon	CBP-PRVO1	ADB1203FE
Marathon	CBP-RNO1	ADB1312
Fritec	CFD-F120	ADB1312
Fritec	CFD-F280	ADB1311
Bendix	K070796	ADB1369
Meritor	KIT195020	ADB1525FE
Meritor	KIT225020	ADB1526
Meritor	KIT2252H2CD	ADB1311
Meritor	MDP5019	ADB1312
Meritor	MDP5038	ADB1407AFE
Meritor	MDP5042	ADB1312
Meritor	MDP5060	ADB1310AFE
Meritor	MDP5061	ADB1312
Meritor	MDP5065	ADB1407FE
Meritor	MDP5097	ADB1310FE
Van Hool	N508206044	ADB1407FE
Van Hool	N508206046	ADB1407AFE
Van Hool	N508206051	ADB1310AFE
Van Hool	N508206052	ADB1310FE
WVA	29179	ADB1203AFE
WVA	29179	ADB1203FE
WVA	29158	ADB1369
WVA	29120	ADB1441
WVA	29143	ADB1527
WVA	29210	ADB1407AFE
WVA	29210	ADB1407FE
WVA	29156	ADB1310AFE
WVA	29156	ADB1310FE
WVA	29187	ADB1311
WVA	29090	ADB1312
WVA	29155	ADB1525FE
WVA	29150	ADB1526
WVA	29088	ADB1518
WVA	29159	ADB1438
WVA	29141	ADB1517

# Engineered For Maximun Braking Power and Minimum Cost Per Mile.



# Drum Brake Block

The first choice of demanding, quality-conscious fleets



### **RSD Drum Brakes**

Specifically designed to meet the FMVSS 121 RSD regulation



## Air Brake CV Pads

Enhanced durability for long lasting performance



# Stop Box Kits

The complete braking solution – eliminates guesswork and parts hunting



### **TECHNICAL INFORMATION**







